



Cart/Category	Acct Code CO-CBS1-BREWHSE			LIC Cost		
		Brewer Hose Damaged or Missing-PARTS & LABOR	\$	86.25		
CBS1	CO-CBS1-CUS	CUSTOM-For Items not covered in Schedule		TBD		
CBS1	CO-CBS1-HWH	Hot Water Heater Damaged or Missing-PARTS & LABOR	\$	402.50		
CBS1	CO-CBS1-IBLID	Elkay Ice Bin Lid Damaged or Missing-PARTS	\$	402.50		
CBS1	CO-CBS1-MKIT	Maintenance Kit Damaged or Missing-PARTS	\$	258.75		
CBS1	CO-CBS1-PNTCN	Canopy Damaged-Repaint-PARTS & LABOR	\$	632.50		
CBS1	CO-CBS1-PNTW	Wing Wall Damaged-Repaint-PARTS & LABOR	\$	920.00		
CBS1	CO-CBS1-PNTWCV	Wing Wall Cover Panel Damaged-Repaint-PARTS & LABOR	\$	402.50		
CBS1	CO-CBS1-SHF	Missing Shelf(s)-PARTS	\$	143.75		
CBS1	CO-CBS1-SO	60 AMP SO Damaged or Missing-PARTS & LABOR	\$	1,035.00		
CBS1	CO-CBS1-SOASM	60 AMP SO Cord Assembly (SO&PLUG) Damaged or Missing-PARTS & LABOR	\$	1,782.50		
CBS1	CO-CBS1-SOPLUG	60 AMP SO Plug Damaged or Missing-PARTS & LABOR	\$	747.50		
CBS1	CO-CBS1-TCAN	Slim Jim Trash Can Missing-PARTS	\$	69.00		
CBS1	CO-CBS1-VNP	Veneer Panel Damaged and needs to be replace (not incl. frame)-PARTS & LABOR	\$	2,070.00		
General	CO-CLEAN	Store Not Cleaned-Extra Cleaning Charge-LABOR	\$	402.50		
General	CO-CLEAN-CUS	CUSTOM-For Items not covered in Schedule		TBD		
CMB1	CO-CMB1-BREWHSE	Brewer Hose Damaged or Missing-PARTS & LABOR	\$	86.25		
CMB1	CO-CMB1-CUS	CUSTOM-For Items not covered in Schedule		TBD		
CMB1	CO-CMB1-FWAND	Flojet Wand Damaged or Missing-PARTS	\$	97.75		
CMB1	CO-CMB1-HWH	Hot Water Heater Damaged or Missing-PARTS & LABOR	\$	402.50		
CMB1	CO-CMB1-IBLID	Elkay Ice Bin Lid Damaged or Missing-PARTS	\$	402.50		
CMB1	CO-CMB1-MHSE	Missing SS Hose to Mastrena-PARTS & LABOR	\$	86.25		
CMB1	CO-CMB1-MKIT	Maintenance Kit Damaged or Missing-PARTS	\$	258.75		
CMB1	CO-CMB1-PNTCN	Canopy Damaged-Repaint-PARTS & LABOR	\$	632.50		
CMB1	CO-CMB1-PNTW	Wing Wall Damaged-Repaint-PARTS & LABOR	\$	920.00		
CMB1	CO-CMB1-PNTWCV	Wing Wall Cover Panel Damaged-Repaint-PARTS & LABOR	\$	402.50		
CMB1	CO-CMB1-SHF	Missing Shelf(s)-PARTS	\$	143.75		





Cart/Category	Acct Code			LIC Cost	
CMB1	CO-CMB1-SO	60 AMP SO Damaged or Missing-PARTS & LABOR	\$	1,035.00	
CMB1	CO-CMB1-SOASM	60 AMP SO Cord Assembly (SO&PLUG) Damaged or Missing-PARTS & LABOR	\$	1,782.50	
CMB1	CO-CMB1-SOPLUG	60 AMP SO Plug Damaged or Missing-PARTS & LABOR	\$	747.50	
CMB1	CO-CMB1-VNP	Veneer Panel Damaged and needs to be replace (not incl. frame)-PARTS & LABOR	\$	2,070.00	
CMC1	CO-CMC1-BREWHSE	Brewer Hose Damaged or Missing-PARTS & LABOR	\$	86.25	
CMC1	CO-CMC1-CUS	CUSTOM-For Items not covered in Schedule		TBD	
CMC1	CO-CMC1-HWH	Hot Water Heater Damaged or Missing-PARTS & LABOR	\$	402.50	
CMC1	CO-CMC1-IBLID	Elkay Ice Bin Lid Damaged or Missing-PARTS	\$	402.50	
CMC1	CO-CMC1-MHSE	Missing SS Hose to Mastrena-PARTS & LABOR	\$	86.25	
CMC1	CO-CMC1-MKIT	Maintenance Kit Damaged or Missing-PARTS	\$	258.75	
CMC1	CO-CMC1-PNTCN	Canopy Damaged-Repaint-PARTS & LABOR	\$	632.50	
CMC1	CO-CMC1-PNTW	Wing Wall Damaged-Repaint-PARTS & LABOR	\$	920.00	
CMC1	CO-CMC1-PNTWCV	Wing Wall Cover Panel Damaged-Repaint-PARTS & LABOR	\$	402.50	
CMC1	CO-CMC1-PRACP	Pitcher Rinser Faucet Adapter Assembly Missing-PARTS & LABOR	\$	212.75	
CMC1	CO-CMC1-SHF	Missing Shelf(s)-PARTS	\$	143.75	
CMC1	CO-CMC1-SO	60 AMP SO Damaged or Missing-PARTS & LABOR	\$	1,035.00	
CMC1	CO-CMC1-SOASM	60 AMP SO Cord Assembly (SO&PLUG) Damaged or Missing-PARTS & LABOR	\$	1,782.50	
CMC1	CO-CMC1-SOPLUG	60 AMP SO Plug Damaged or Missing-PARTS & LABOR	\$	747.50	
CMC1	CO-CMC1-VNP	Veneer Panel Damaged and needs to be replace (not incl. frame)-PARTS & LABOR	\$	2,070.00	
CND1	CO-CND1-CADY	Condiment Caddy Damaged or Missing-PARTS	\$	517.50	
CND1	CO-CND1-CAN	Condiment Caddy Damaged or Missing-PARTS	\$	40.25	
CND1	CO-CND1-CUS	CUSTOM-For Items not covered in Schedule		TBD	
CND1	CO-CND1-TRC	Trash Chute(s) Missing-PARTS	\$	46.00	
Custom	CO-CUS	CUSTOM-For Items not covered in Schedule		TBD	
Equipment	CO-EQUP-AMB	EQUIPMENT-Countertop Ambient Missing or Damaged-PARTS	\$	747.50	
Equipment	CO-EQUP-BREW	BUNN Brewer Damaged or Missing-PARTS & LABOR	\$	1,782.50	
Equipment	CO-EQUP-BREW-CUS	CUSTOM-For Items not covered in Schedule		TBD	





Cart/Category	Acct Code			LIC Cost	
Equipment	CO-EQUP-BREW-DTRY	Brewer Drip Tray Damaged or Missing-PARTS & LABOR	\$	172.50	
Equipment	CO-EQUP-SERV-DTRY	Server Drip Tray Damaged or Missing-PARTS & LABOR	\$	172.50	
Equipment	CO-EQUP-SRV	BUNN Server Damaged or Missing-PARTS	\$	575.00	
Equipment	CO-EQUP-STAND	BUNN Server Stand Damaged or Missing-PARTS	\$	402.50	
Equipment	CO-EQUP-PITRS	Pitcher Rinser Assembly Damaged or Missing-PARTS	\$	185.00	
Jockey Box	CO-JOCK-CUS	CUSTOM-For Items not covered in Schedule		TBD	
Jockey Box	CO-JOCK-CVR	Cover missing or damaged-PARTS & LABOR	\$	86.25	
Jockey Box	CO-JOCK-NR	Box Missing and Not Returned-PARTS	\$	1,552.50	
Jockey Box	CO-JOCK-UNI	Unistruct Removed and Missing-PARTS & LABOR	\$	138.00	
General	CO-KEYS	Missing Keys for Cooler and Store-PARTS	\$	40.25	
MST1	CO-MST1-CUS	CUSTOM-For Items not covered in Schedule		TBD	
MST1	CO-MST1-HWH	Hot Water Heater Damaged or Missing-PARTS & LABOR	\$	402.50	
MST1	CO-MST1-MHSE	Missing SS Hose to Mastrena-PARTS & LABOR	\$	86.25	
MST1	CO-MST1-MKIT	Maintenance Kit Damaged or Missing-PARTS	\$	258.75	
MST1	CO-MST1-PNTCN	Canopy Damaged-Repaint-PARTS & LABOR	\$	632.50	
MST1	CO-MST1-PNTW	Wing Wall Damaged-Repaint-PARTS & LABOR	\$	920.00	
MST1	CO-MST1-PNTWCV	Wing Wall Cover Panel Damaged-Repaint-PARTS & LABOR	\$	402.50	
MST1	CO-MST1-SO	60 AMP SO Damaged or Missing-PARTS & LABOR	\$	1,035.00	
MST1	CO-MST1-SOASM	60 AMP SO Cord Assembly (SO&PLUG) Damaged or Missing-PARTS & LABOR	\$	1,782.50	
MST1	CO-MST1-SOPLUG	60 AMP SO Plug Damaged or Missing-PARTS & LABOR	\$	747.50	
MST1	CO-MST1-VNP	Veneer Panel Damaged and needs to be replace (not incl. frame)-PARTS & LABOR	\$	2,070.00	
POS1	CO-POS1-CUS	CUSTOM-For Items not covered in Schedule		TBD	
POS1	CO-POS1-MENU	Missing or Damaged Menu(s) (N/C Bracket(s))-PARTS	\$	345.00	
POS1	CO-POS1-PNTW	Wing Wall Damaged-Repaint-PARTS & LABOR	\$	920.00	
POS1	CO-POS1-PNTWCV	Wing Wall Cover Panel Damaged-Repaint-PARTS & LABOR	\$	402.50	
POS1	CO-POS1-SHF	Missing Shelf(s)-PARTS	\$	143.75	
POS1	CO-POS1-VNP	Veneer Panel Damaged and needs to be replace (not incl. frame)-PARTS & LABOR	\$	2,070.00	





Cart/Category	Acct Code		LIC Cost	
POS1	CO-POS1-XCRD	Missing Extension Cord-PARTS	\$	69.00
POS1	CO-POS1-XCRDCV	Extension Cord Cover Damaged or Missing-PARTS	\$	86.25
SCW1	CO-SCW1-WRCK	Warming Rack Damaged or Missing-PARTS	\$	200.00
TWW1	CO-TWW1-CUS	CUSTOM-For Items not covered in Schedule		TBD
TWW1	CO-TWW1-PNTCN	Canopy Damaged-Repaint-PARTS & LABOR	\$	402.50
TWW1	CO-TWW1-PNTCS	Chassis Damaged-Repaint-PARTS & LABOR	\$	805.00
TWW1	CO-TWW1-WRCK	Warming Rack Damaged or Missing-PARTS	\$	230.00
TWW1	CO-TWW1-XCRD	Missing Extension Cord-PARTS	\$	69.00
TWW1	CO-TWW1-XCRS	Missing Extension Cord Splitter-PARTS	\$	69.00